

Ross Fed 28 #42

H-28-20N-1W

COTTON PETRO. CORP.

F

30-043-20700

11-29-83

F. Loc. 1980/N;470/E

Elev. 6938 GL

Spd.

Comp.

TD

PB

Casing S. @ W Sx. Int. @ W Sx. Pr.

Cu. ft.

Cu. ft.

Cu. ft.

Csg. Perf.

Prod. Stim.

T Gas
R
A
N
S

BO/D

Grav.

1st Del. Gas

I.P. MCF/D After Hrs. SICP

PSI After

Days GOR

1st Del. Oil

TOPS

NiTD X

Well Log

TEST DATA

Ojo Alamo

C-103

Plat X

Schd.

PC

Q

PW

PD

D

Ref.No.

Kirtland

C-104

Electric Log

Fruitland

C-122

Pictured Cliffs

Ditr

Dfa

Chacra

Datr

Dac

Cliff House

Menefee

Point Lookout

Mancos

Gallup

Greenhorn

Dakota

Entrada

Acres 40

P
o
o
i

WC Gal

Co.

SA

S

28

T

20N

R

1W

U

H

Oper. Cotton Petro. Corp.

Lse.

Ross Fed 28

No. 42

04 JUN. 1984

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Cotton Petroleum Corporation
 3773 Cherry Creek Drive, North #750
 Denver, Colorado 80209

Gentlemen:

Reference is made to the following Applications for Permit to Drill (APD's).

- 1) ~~43-34 Ross Federal, NE-SW section 34~~ *never got APD*
- 2) ~~42-28 Ross Federal, SE-NW section 28~~
- 3) ~~24-27 Ross Federal, SE-SW section 27~~
- 4) ~~32-27 Ross Federal, SW-SW section 27~~

All in T. 20 N., R. 1 W., Sandoval County, New Mexico, lease New Mexico-14624. The subject APD's are hereby rescinded and returned due to the lease expiration on May 31, 1984.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,

/s/ J. Stan McKee

Area Manager

Enclosure

cc:
 BLM, Rio Puerco
RHOCC
 ADO (01537)
 Well file
 DRO 9-1

016:EBeecher:el:6-1-34

RECEIVED

JUN 05 1984

OIL CON. DIV.
 DIST. 3

ABANDONED LOCATION