Form 3160-5 (June 1990)

Do not use this

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

SUBMIT IN TRIPLICATE

FORM APPROVED						
Budget	Bur	cau	No.	100	14-0	13
Expi	res:	M	nch	31,	1993	

		Expires:	March	31, 199	/3
5.	Lease	Designat	ion and	Serial	No.

NM	17009	
TAT.T	11003	

TOTAL HOTIOLO AND HEL ONTO ON WELLS
form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

7. If Unit or CA, Agreement Designation

8. Well Name and No.
Absolut #1

9. API Well No.

30-043-20864

10. Field and Pool, or Exploratory Area

CO1

Counselors GA/DK Ext.
11. County or Parish, State

Sandoval, NM

670' FNL & 1830' FWL Sec. 23, T23N, R6W, NMPM

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Subsequent Report JAN1 4	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice OIL CON DIST	Altering Casing X Other T.D. & Casing	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Citary sine an parinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 5654' reached on \$\mathbb{B}\$-14-91. Finished running IES & CDL logs by Great Guns Logging. T.I.H. and conditioned mud. Laid down drill pipe and collars. Rigged up and ran 125 jts. 4-1/2* 0D, 10.5#, Wildcat *50*, ST&C casing (T.E. 5654.97') set at 5649' RKB. Cemented first stage by pumping 15 bbls mud flush followed by 220 sx 50-50 pos + 2% get and 1/4# cellophane flakes per sack (total cement sturry first stage = 268 cu.ft.). Full mud returns while cementing. Reciprocated casing OK while cementing. Maximum cementing pressure = 500 psi. Bumped plug with 1500 psi - float held OK. Dropped opening bomb and opened stage tool at 4549' RKB. Circulated with rig pump for 2-1/2 hrs. Cemented 2nd stage by pumping 15 bbls mud flush followed by 800 sx 65-35 plus 12% get and 1/4# celloflake per sack followed by 50 sx 50-50 pos + 2% get and 1/4# celloflake per sack (total cement sturry 2nd stage = 1829 cu.ft.). Total cement sturry used in both stages = 2097 cu.ft. Maximum cementing pressure 1200 psi. Full returns while cementing. Circulated good cement to surface (approx. 35 bbls contaminated cement). Closed stage tool with 2500 psi -held OK. *Note: turbolizers a 1683' and 1592'. Set 4-1/2* casing slips. Nippled down BOP, cut off 4-1/2* casing and released rig at 3:30 A.M. 12-15-91.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the training South Entititious or fraudulent statements or representations as to any matter within its jurisdiction.