

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved by  
Budget Bureau No. 1421

5. LEASE DESIGNATION AND NO.

SF-078974

6. IF INDIAN, ALLOTTEE OR TRUST NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 6-22

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

22-24N-7W NYPM

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

DF 7066

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

XX

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Run 25 sacks Class A cement to cover perforations from 5800-5967.


Run 25 sacks Class A cement for plug inside casing 2300-2450.

Perforate at 1950'. Run 100 sacks Class A cement for 300' plug inside and outside casing 1650-1950.

Five sacks Class A cement in 8 5/8" - 5-1/2" annulus.

Ten sacks Class A cement in 5-1/2" with dry hole marker at surface.

Clean up location.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice President

DATE

6-9-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side