

Form 5-331
(May 1980)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-014021-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Stephenson ~~522~~

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Escrito Gallup

11. SEC., T., E., M., OR BLK. AND
SURVEY OR AREA

22-24N-7W NMPM

12. COUNTY OR PARISH 13. STATE

Rio Arriba

New Mexico

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

BCO, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 669 Santa Fe, New Mexico 87501

4. LOCATION OF WELL (Report location clearly and in accordance with Bureau Form 5-331.
See also space 17 below.)
At surface

780 FNL 660 FWL 22-24N-7W NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether D.U.S. GEOLOGICAL SURVEY
FARMINGTON, N. M.)

7140 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☒(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recapture Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

We intend to set a BP above Gallup perforations (5782-6004). We intend to find leak in casing and repair same with cement. Notification of cement job will be made to Minerals Management Service prior to commencement of same. Cement will be allowed to set up a minimum of 48 hours. We will then drill out cement, remove BP, acidize perms if necessary, and place well in operation.

The above intended work was discussed with Richard Bell with Minerals Management Service on September 15, 1982. Mr. Keller with Minerals Management was also notified of our intentions to find the leak in casing.

18. I hereby certify that the foregoing is true and correct

SIGNED

John J. Cassin

TITLE Office Manager

DATE 9/15/82

(This space for Federal use only)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

SEP 17 1982

JAMES F. SIMS
DISTRICT ENGINEER

TITLE

DATE

*See Instructions on Reverse Side

NMOCC

