

Form 9-331a
(Feb. 1961)


(SUBMIT IN TRIPLICATE)

Land Office New Mexico

Lease No. 32 076924

Unit 6

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 15, 19 61

Well No. 1 is located 790 ft. from N line and 1650 ft. from W line of sec. 21

24 N 7W 18R
(Twp.) (Range) (Meridian)
Maricao-Mallup San Arriba County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7265 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On Feb. 23, 1961, displaced hole w/oil ran Gr-Corr log and perf. 6076'-6096' w/a jets/ft. spotted 250 gals oil on peris and some in over nite freed w/50,000 gals lease crane with 50,000 sand. cleaned out with sand pump to 7220 6152'. Ran tag to 4066. Well potentiated after recovery all lead oil for 201 6076 flowing on 22/65, at 550, at 1150 on 3-14-61

I understand that this plan of work must receive approval in writing by the Geological Survey before operation may be commenced.

Company Standard Oil Company of Texas, A Division of California Oil Company

Address Boxer #3, Monahans, Texas

By C. F. Dwyer
C. F. Dwyer
Title District Engineer

