

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Federal <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Federal
3. Address of Operator Box 990, Farmington, New Mexico - 87401	9. Well No. 4 (P&A)
4. Location of Well UNIT LETTER 0 1110 FEET FROM THE South LINE AND 1790 FEET FROM East LINE, SECTION 14 TOWNSHIP 24N RANGE 2W NMPM.	10. Field and Pool, or Wildcat So. Blanco P. C.
15. Elevation (Show whether DF, RT, GR, etc.) 7382' GL	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned as follows:

Spotted a 25 sack cement plug on bottom to cover open hole (3385 - 3460').

Perforated 5 holes at 3212' (base of Ojo Alamo). Spotted a 50 sack cement plug across perfs at 3212' and squeezed.

Shot off 5 1/2" casing at 1087', spotted a 25 sack cement plug on top of stub at 1087', pulled casing.

Spotted a 25 sack cement plug across base of surface casing.

Placed a 10 sack cement plug at surface w/a 4' x 4" P & A marker. P&A completed 10-1-69.

A sundry notice will follow when location is cleaned up.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F. H. WOOD

TITLE Petroleum Engineer

DATE 10-31-69

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: