

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03595

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☐ OTHER

7. UNIT AGREEMENT NAME

None

2. NAME OF OPERATOR

8. FARM OR LEASE NAME

Judy

3. ADDRESS OF OPERATOR

9. WELL NO.

1

P.O. Box 669 Santa Fe, N.M. 87501

10. FIELD AND POOL, OR WILDCAT

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Wildcat

790 FEL 790 FSL Sec 17 T24N R7W NMPM

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

17-24N-7W NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 7305

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐FILL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETION ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☒ABANDON* ☒SHOOTING OR ACIDIZING ☐ABANDONMENT* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Squeeze existing perforations, (5032-5093), with 50 sacks cement.

Perforate at 3750 and squeeze with 150 sacks cement if circulation achieved. If unable to circulate perforate at 3200 and cement between perforations.

Perforate Chacra with two shots per foot at selected intervals from 3468-3678.

If commercial production not obtained spot cement plug over perforations, (3468-3678), cover Ojo Alamo inside and outside casing, and set 10 sack plug in 10 3/4 - 5 1/2 annulus and ten sacks inside 5 1/2 casing with dry hole marker at surface.



Original Signed by

LARRY R. BLISS, CPA

18. I hereby certify that the foregoing is true and correct

SIGNED

Santa Fe, New Mexico 87501

TITLE

President

DATE

4-24-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side