UNITE	Budget Bureau No. 42-R358.4. Form Approved.  Land Office Lease No. 12-235  Lease No. 12-235  Unit Unit Lease No. 12-235  Unit Lease No. 12-2535  Unit Lease No. 12-2535  Unit Lease No. 12-2535  Unit Lease No. 12-2535
NOTICE OF INTENTION TO DRILL  NOTICE OF INTENTION TO CHANGE PLANS  NOTICE OF INTENTION TO TEST WATER SHUT-OFF  NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL  NOTICE OF INTENTION TO SHOOT OR ACIDIZE  NOTICE OF INTENTION TO PULL OR ALTER CASING  NOTICE OF INTENTION TO ABANDON WELL	SUBSEQUENT REPORT OF WATER SHUT-OFF.  SUBSEQUENT REPORT OF SHOOTING OR ACCOUNTY SUBSEQUENT REPORT OF ALTERING CASING FOLLOWING SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR ON EXTLUSIVE SUBSEQUENT REPORT OF ABANDONMENT.  SUPPLEMENTARY WELL HISTORY  Drill to Tooks
Well No. 1 is located 1650 ft. from SE/A NE/A Sec 15 (W Sec. and Sec. No.) (Twp.) (R	ange) (Meridian)  Subdivision) (State or Territory)
DETAILS OF WORK  (State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)  Fan D.S.T. #1 9-16-62 3995-4047 T.O. 1 hr. weak blow air incadiately continued throughout test. That in one hour I by 2265 pai, IF 30 pai, FF 60 pai, one hour FSI 1220 pai, F by 2065 pai, recovered 60° water cut drig mud.  Tan D.S.T. #2 9-16-62 3952-4047 Opened tool 5 min Fritial shart in 30 min; tool open 1 1/2 hrs WDA inred increased to good blow; I by 2035 pai, I 60 pai, IF 375 pai, ISI 1270 pai/30 min. FSIF 1180 pai/1 hr. F by 1980 pai, recovered 775° water and water cut drig mad.  Company  Reifern Development Corp.  DIST. 3	

os 1747

Midlami, Temp

Address .....

By Original signed by T. A. Dugan

Title Conculting Ingineer