

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Merrion Oil & Gas Corporation

3. Address and Telephone No.

P. O. Box 840, Farmington, NM 87499 505/327-9801

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FNL & 990' FEL Sec 17, T24N, R6W

5. Lease Designation and Serial No.

SF-078886

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

Canyon Largo Unit

8. Well Name and No.

Canyon Largo 121

9. API Well No.

10. Field and Pool, or Exploratory Area

Devils Fork Mesaverde

11. County or Parish, State

Rio Arriba, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☒ Other Repair Csg Leak

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1-25-92 Mill out tight spot 630'-635'.

1-28-92 Isolate leaky sqz hole @ 4250' and csg leaks 586'-645'.

1-30-92 Sqz old sqz holes @ 4250' w/ 15 sx neat 'G'.
Sqz 586'-645' w/ 35 sx 'G' w/ 2% CaCl.

2-2-92 Drill out cmt. Press test csg to 500 psi, ok.
Swab test, ok. Pull RBP and clean out to PBTD.

2-8-92 Acidize Mesaverde perms 4312'-4322' w/ 500 gal 7-1/2% HCl. Swab back. Return well to production.

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title

Petroleum Engineer

Date

3/10/92

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

[Signature]

Title

NMOCD

Date

MAR 11 1992

FARMINGTON RESOURCE AREA

BY

[Signature]