

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-03595

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Escrito Gallup

8. FARM OR LEASE NAME

Escrito Gallup Unit

9. WELL NO.

5 (Formerly Eliz #3)

10. FIELD AND POOL, OR WILDCAT

Escrito Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

18-24N-7W NMPM

12. COUNTY OR PARISH

Rio Arriba

13. STATE

NM

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Bco, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 669, Santa Fe, N.M. 87501

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1500 FNL and 790 FWL Sec 18 T24N R7W NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 7099

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

FRACTURE TREAT

XXX

SHOOT OR ACIDIZE

XXX

REPAIR WELL

XXX

(Other) shut off water saturated sands

PULL OR ALTER CASING

☐

MULTIPLE COMPLETE

☐

ABANDON*

☐

CHANGE PLANS

☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

FRACTURE TREATMENT

☐

SHOOTING OR ACIDIZING

☐

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

☐

ALTERING CASING

☐

ABANDONMENT*

☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pull tubing. Re-run with packer and set at 5880'. Squeeze existing perforations, (5917-5970 that have water in them), with 30 barrels of diesel and 200 sacks of cement. Drill out, or wash out cement in hole and try to break down old perforations with acid. If unsuccessful, perforate upper portion of Mayre and frac with 15,000 to 20,000 #'s sand.

Perforate Skelly zone selectively between 5726-5836. Set retrievable bridge plug at 5880 and frac with approximately 60,000 #'s 10-20 sand. Remove bridge plug and place well back in operation.

RECEIVED

APR 27 1973

U.S. GEOLOGICAL SURVEY



Original Signed By

18. I hereby certify that the foregoing is true and correct

SIGNED

Santa Fe, New Mexico 87501

TITLE

President

DATE

4-24-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: