UNITED STATES DEPARTMENT OF THE INTERIOR

Sundry Notices and Reports on Wells	
 Name of Operator Meridian Oil Inc. 3. Address & Phone No. of Operator Box 4289, Farmington, NM 87499 (505) 326-9700 	_ 8. Well Name & Number Jicarilla 126 S #13) 9. API Well No.
4. Location of Well, Footage, Sec, T, R, M. 1850'S, 990'E Sec. 12, T-24-N, R-4-W, NMPM	10.Field and Pool Basin Fruitland Coal 11.County and State Rio Arriba County, NM
Notice of Intent Abandonment X Recompletion X Subsequent Report X Plugging Back Casing Repair	of Action Change of Plans New Construction Non-Routine Fracturing
13. Describe Proposed or Completed Operations 12-10-90 MOL&RU. 12-11-90 Wellhead has csg. failure @ top of	head failure. Circ to surface. Cut off Set FBP @ 15'. Cut off csg L. Top of CIBP @ 3000'. PT, ettings. Failure from top KCl wtr. SDFN. /15 min, ok. Swabbed. 2793-96', 2808-12', 2912', 2922-31', 2968-71', L. BD perfs. TOOH w/tool.
14. I hereby certify that the foregoing is true Signed Signed Silla full Title Regulatory	Affairs Date 12-20-90
(This space for Federal or State office use) ACCEPTED FOR RECORD	

TITLE JAN 2 2 1991

FARMINGTON DESQUERCE AREA

APPROVED BY _

CONDITION OF APPROVAL, IF ANY:

