

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries);

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Ojo Alamo	2510'	2670'	White, cr-gr ss.	Ojo Alamo Kirtland Fruitland Pic. Cliffs	2510' 2670' 2814' 2994'	
Kirtland	2670'	2814'	Gry sh interbedded w/tight, gry, fine-gr ss.			
Fruitland	2814'	2994'	Dk gry-gry carb sh, coal, grn silts, light-med gry, tight, fine gr ss.			
Pictured Cliffs	2994'	3150'	Bn-Gry, fine grn, tight ss.			

38. GEOLOGIC MARKERS