COPIES: 5-USGS 3-Denver 1-File

Form 9-881 a (Feb. 1961)

R7W

T 24

N

(SUBMIT IN TRIPLICATE)

Land	Offic	Sı	inte.	.Fe	
Loase	No.	SF	0789)5 <u>9</u>	

Budget Bureau No. 42-R358.4.



Form Approved.

	······································	1 0	
NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE	PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WA	ATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRIL	L OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT	OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OF	ALTER CASING	SUPPLEMENTARY WELL HISTORY	·····
NOTICE OF INTENTION TO ABANDO	N WELL		
(INDIC	CATE ABOVE BY CHECK MA	ARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
		January 2,	, 183
Federal /ell No. 1-7 is local	ated 990 ft. fro	om. $\frac{E}{ S }$ line and990 ft. from $\frac{E}{ S }$ line of	sec. 7
SE/4 Section 7		(2) NINDM	
(14 Sec. and Sec. No.)	(Twp.)	(Range) (Meridian)	
Basin Dakota	Rio A	rriba New Mexido F	CEIV
(Field)	(Count	ty or Subdivision) New Martine Property Property	
	1.0	i i Grant e r	
he elevation of the derric	ck floor above sea	level is ft. 7330 * G. L.	AN 20 198
	DFT	AILS OF WORK	
		AILS OF WORK	
			Talindigae S
	ing points, and a	sizes, weights, and lengths of proposed casings; indicate muddhill other important proposed work)	San San Ber Bergerie en
Plugged and abandon perforations. Lay Set 25 am cement pl	ned by setting down tbg. Pullug at casing	aixes, weights, and lengths of proposed casings; indicate muddinal other important proposed work) a 25 ax cement plug through the Dailled and parted 4-1/2" casing @ 224 stub. Set 25 ax cement plug, set a set 4" above surface.	tota
Plugged and abandon perforations. Lay Set 25 ax cement pl surface w/P &A mari	ned by setting down tbg. Pulling at casing a ker of 4" pipe	a 25 sx cement plug through the Dai lled and parted 4-1/2" casing @ 224' stub. Set 25 sx cement plug, set a	tota
Plugged and abandon perforations. Lay Set 25 ax cement pl surface w/P &A mari Work was performed	ned by setting down thg. Pulling at casing a ker of 4" pipe by Bedford, In	a 25 sx cement plug through the Daliled and parted 4-1/2" casing & 224 stub. Set 25 sx cement plug, set a set 4' above surface. nc. Job completed 12/21/62 REFEL JAN 25 Krahl, USGS.	VED 1963
Plugged and abandon perforations. Lay Set 25 ax cement plugged are well and a maring work was performed. Verbal approval grant of the set of t	ned by setting down thg. Pulling at casing a ker of 4" pipe by Bedford, In anted by Bick in the british must receive approval	a 25 sx cement plug through the Dailled and parted 4-1/2" casing @ 224" stub. Set 25 sx cement plug, set a set 4" above surface. nc. Job completed 12/21/62 REFEL JAN 25	VED 1963
Plugged and abandon perforations. Lay Set 25 ax cement pl surface w/P &A mari Work was performed	ned by setting down the. Pulling at casing a ker of 4" pipe by Bedford, In anted by Dick in the must receive approval LORATION, INC.	a 25 sx cement plug through the Daliled and parted 4-1/2" casing & 224 stub. Set 25 sx cement plug, set a set 4' above surface. nc. Job completed 12/21/62 REFEL JAN 25 Krahl, USGS.	VED 1963
Plugged and abandon perforations. Lay Set 25 ax cement plusurface w/P &A mark work was performed. Verbal approval grand understand that this plan of work was performed.	ned by setting down thg. Pullug at casing ker of 4" pipe by Bedford, In anted by Dick look must receive approval LORATION, INC.	a 25 sx cement plug through the Dalilled and parted 4-1/2" casing @ 224 stub. Set 25 sx cement plug, set s, set 4' above surface. Inc. Job completed 12/21/62 REFE	VED 1963
Plugged and abandon perforations. Lay Set 25 sx cement plugged w/P &A mark was performed. Work was performed. Verbal approval great and the standard of the standard standar	ned by setting down thg. Pullug at casing ker of 4" pipe by Bedford, In anted by Dick look must receive approval LORATION, INC.	a 25 sx cement plug through the Daidled and parted 4-1/2" casing @ 224's stub. Set 25 sx cement plug, set a set 4' above surface. Inc. Job completed 12/21/62 REFE	VED 1963