Form 9-331 (May 1963)		UNITED STATES	SUBMIT IN TRIPLICATE (Other dustructions on re	Form approved. Budget Bureap-No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.			
		MENT OF THE INTER EOLOGICAL SURVEY	KIUK rerse side)	SF-078959		SELIN NO.	
	HOLL ARGINE	ces and reports	ON WELLS	6. IF INDIAN, ALLO	TTEE 68 1	TOISE NAME	
(Do not use	를 취실 수 기계 기계 기	· · · · · · · · · · · · · · · · · · ·					
1.	7. UNIT AGESTAN	T NAME	<u> </u>				
OIL CA	S OTHER			= = = = = = = = = = = = = = = = = = = =	- 111	<u> 구</u> 축설별	
2. NAME OF OPERAT	TOB			8. FARM OF TASE	- ANNE		
BCO, Inc	r. A.T.O.D.			Federal 1-	7 3		
		a Fe, New Mexico	375 01	1 1	n yed		
4. LOCATION OF WE See also space 1	10. FOED AND FO	L, OR ATL	Husa				
At surface	Dufero Per	لملًا عم	tota (C.				
				11. SEC., T., R., M., SURVEY OF D	OR BLK. A	NOTE TO	
99 0' FS	L 990' FEL	Section 7 T 24N F	R7W N M P M.	7-24N, 7W-N	Г.М.Р.1	e i e e M & i e	
14. PERMIT NO.	770 150	15. ELEVATIONS (Show whether		12. COUNTY OR PA		STATE	
		7344 KB		Rio Arriba	2 No	ew-Hexico	
16.	Check Ap	propriate Box To Indicate	Nature of Notice, Report, or	Other Data = 15 3	red .	2 - 7 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	
	NOTICE OF INTENT			SECULAR THOUSE	1	Rino Rino Litto Rino	
TEST WATER SI	HCT-OFF P	ULL OR ALTER CASING	WATER SHUT-OFF	EEPAIR!	NG WELL		
FRACTURE TREA	ر <u>- ب</u>	ULTIPLE COMPLETE	FRACTURE TERATMENT	Turesin	O CYAINO		
SHOOT OR ACIDI	IZE	BANDON*	SHOOTING OR ACIDIZING	X 3 B Auguspo	MENT		
REPAIR WELL		HANGE PLANS		ts of multiple complet		- 615 2 를 - 15 - 기토	
(Other)	SED OR COMPLETED OPER	RATIONS (Clearly state all perting	ent details and alse pertinent date	pletion Report and Logs, including estimated	date of	starting and	
proposed wor nent to this w	k. If well is direction or k.) *	nally drilled, give subsurface lo	extions and measured and true vert	icm debths tot off wife	rkers and	.zones sertif. 記せ音楽 び	
			2 1/8 glass shot at 6				
			4, 10, 6200, 6190, 84. 6, 68, 62, 56, 44, 35.		10 1		
	9, 05, 5995,		0, 00, 02, 50, 44, 55,	ting the time	Federal	* 다립 3 문사는	
				nrs e		ing c inite ional	
			6947-55 with 25 sacks	s of distributed	de si	Tagg Tagg Talu Talu Tagg	
		ueeze ‡ Bbl slurry : c at 5574 and sque	ezed 5970-6298 perfs v	v/120 India 3		2 × 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
sacks Cla		750	Ela Cilia Marid				
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	,	11.1. 31.1.6 0000	
	lled cement. Sew P.		pped drilling at 6275	while	S. C.		
SCILL III	cement. New 1	BID 0215.				ਤਾਜ਼2ਜ਼ \ ਤਿੰਤੇਜ਼	
•	•		ed 6224-38. Treated w/	/500		and and	
gals 7.5%	MCA acid. Swa	abbed heavy mud.				PTT PTT CUP	
8-10-78 Squ	eezed 5970-62	75 w/250 sacks Class	s R cement.				
0 10 70 bqu	cc2cu 3770 02	, with the second of the second secon	o b cement.	(\$\frac{1}{2}\text{3.2}{2}\text{3.2}{2}		9 0 0 1 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 0 0 0 1 0	
			ring the spring of 197	VC 2 -	110	leaf Any Any dunt dunt	
	_	-78 is succesful we	will perforate, and f	rac Es	3 3	18. 18. 18. 18. 18. (
the Gallu	p•			that)	01 9 01 9 11 10	of h	
1S. I bereby certify	that the foregoing is	true and correct			7 0 1 1 0 1 1 1 0 1 1 1 1 1 1 1 1 1 1 1	<u> </u>	
2/2	are R.B.	9-21-78 _{TLE}	President	DATE OF	18 11 18 11 11 11	27 E	
SIGNED ALL				DATE EL	7 5		
(This space for	Federal or State offic	re us e)		alulte hinos puoli	m5)	ELEST TARE THE TOTAL	
APPROVED BY CONDITIONS (OF APPROVAL, IF A	TITLE		DATE	7 0 1 1 8.t		
	•			성 중 즉 원	0.3	2 m 5	