5 BLM 1 File (Alb)

TYPE OF SUBMISSION

Notice of Intent

Subsequent Report

Form 3160-5 (June 1990) UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

		Expires	: Ma	ıch	31, 1	993	
5. L	case	Designa	tion i	and	Seri	al No	٥.

6. If Indian, Allottee or Tribe Name

Change of Plans

New Construction

Non-Routine Fracturing

3 T3 4	α
NM	-06855

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Use "APPLICATION FOR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well	
Oil X Gas Well Other	8. Well Name and No.
2. Name of Operator	J.R. Anderson #1
Dugan Production Corp.	9. API Well No.
3. Address and Telephone No.	30-039-05705
P.O. Box 420, Farmington, NM 87499 (505) 325-1821	10 Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	South Blanco PC
1550' FSL & 1490' FEL	11. County or Parish, State
Sec. 33, T25N, R3W	Rio Arriba, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER DATA

	Casing Repair	L_ Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other long-term shut-in	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state al	1 pertinent details, and give pertinent dates, including estimated date of starting a	any proposed work. If well is directionally drilled,

Abandonment

Recompletion

Plugging Back

TYPE OF ACTION

This well is unable to produce in paying quantities under existing market conditions. A long-term shut-in status is requested.

SEP1. 51993

OIL CON DIV

OIL CON. DIV.

hereby certify that the foregoing is true and correct Signed 1000 00000000000000000000000000000000	Title	Operations Manager	Date	6/30/93
This space for Federal or State office use) SHIRLEY MONDY Approved by Conditions of approval, if any:	Acting Tide	AREA MANAGER PIO PUENCO RESOURCE AREA	Date	SEP 1 0 1993
This approval expires	4/1/	14.		

MIG C 1 File (Alb)

Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

PORM APPROVED					
	Budget Bureau No. 1004-0135				
	Expires: March 31, 1993				
5.	Lease Designation and Serial No.				

Lease	Designation	end	Serial	No

NM 06855

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposale

6.	lf	Indian,	Allottec	OF	Tribe	Name

(Note: Report results of multiple completion on Well

SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation		
1. Type of Well			
Oil Gas Well Other	8. Well Name and No.		
2. Name of Operator	J.R. Anderson #1		
Dugan Production Corp.	9. API Well No.		
3. Address and Telephone No.	30-039-05705		
P.O. Box 420, Farmington, NM 87499 (505) 325-1821	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	South Blanco PC		
1550' FSL & 1490' FEL	11. County or Parish, State		
Sec. 33, T25N, R3W			
	Rio Arriba, NM		

TYPE OF SUBMISSION			TYPE OF ACTION	
Notice of Intent	7 m3 & m3	Hart Hart to X Abendonm	ent	Change of Plans
	de Central Contraction	Recomplete	~~~	New Construction
Subsequent Report		Plugging B	<u>~</u>	Non-Routine Fracturing
	JUL 2	6 1385 □/ ☐ Casing Rep	mair	Water Shut-Off
L.J Final Abendonment No	xtice	Altering Co	using	Conversion to Injection
α	നെ ഭത	7 U Other		Dispose Water
~	シnm のごす	NO MINUO	(N	ote. Report results of multiple completion on

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plan to plug as follows:

- 1. Set cast iron bridge plug below Pictured Cliffs top Spot Class B cement on top of plug to cover (3487'). Pictured Cliffs and Fruitland top (3355').
- 2. Spot 100' Class B cement plug to cover Ojo Alamo top (3050') inside pipe.
- 3. Perforate 50' below surface casing (174'). Pump Class B cement + 4% gel down casing and circulate to surface.

Class B cement weighs 15.6 lb./gal. and yields 1.18 cu. ft./sk. Class B +4% gel weighs 14.1 lb./gal. and yields 1.55 cu. ft./sk. All plugs will be spotted with water.

14. I hereby certify that the foregoing is true and correct		=====	
Signed John Wexander	Tide Operations Manager	Date _	12/9/94
(This space for Federal or State office use)	16		JUL 2 5 1995
Approved by Kerte Kent Conditions of approval, if any:	Chief, Lands and Mineral Resources	Dute _	

Tide 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CONDITIONS OF APPROVAL FOR PERMANENT ABANDONMENT

Operator <u>DUGAN PRODUCTION CORP</u> Well Name J.R. ANDERSON #1

- 1. Plugging operations authorized are subject to the "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. For wells on Federal leases, Al Yepa with the Cuba Field Office is to be notified at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 289-3748. Office hours are 7:45 a.m. to 4:30 p.m.

For wells on Jicarilla leases notify Erwin Elote with the Jicarilla Apache Tribe at least 24 hours (48 hours if possible) before the plugging operations commence. His phone number is (505) 759-3242.

- 3. Blowout prevention equipment is required.
- 4. The following modifications to your plugging program are to be made :

The cast iron bridge plug must be set within 50 to 100 feet of the Pictured Cliffs perforations and capped with a minimum of 50 feet of cement.

The cement plug for the Fruitland Formation must extend 50 feet above and below the top of the formation.

The cement plug for the Ojo Alamo Formation must extend 50 feet above and below the top of the formation.