

20-039-05737

J 12-18-58

F. Loc. 1980/N; 660/E

Casing S. 104 @ 305 W 300 Sx. Int. @ W Sx. Pr. 52 @ 629 W 739 Sx. T. 2 - 6253
 Csg. Perf. 6142-6252 Prod. Stim. 50F

I.P. 87 BO/D MCF/D After Hrs. SICP PSI After Days GOR 1735 Grav. 41.6 1st Del. 4-13-59

TOPS		NITD	X	Well Log	TEST DATA						
Kirtland		C-102		Plat	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland		C-103		Electric Log	DATE	GOR	BBLS	DATE	GOR	BBLS	Ref. No.
Pictured Cliffs	<u>2785</u>	C-104		C-110 <u>4-13-59</u>	<u>5/1/59</u>	<u>2120</u>	<u>75</u>	<u>12/5/69</u>	<u>9092</u>	<u>13</u>	<u>21/59</u>
Cliff House	<u>4347</u>				<u>1/3/60</u>	<u>1300</u>	<u>57</u>	<u>7/14/70</u>	<u>14833</u>	<u>6</u>	
Menefee	<u>4420</u>	Ditr		Dfa	<u>9/24/60</u>	<u>4059</u>	<u>38</u>	<u>7/24/71</u>	<u>15000</u>	<u>6</u>	
Point Lookout	<u>4964</u>	Datr		Dac	<u>5/8/61</u>	<u>5477</u>	<u>30</u>	<u>8/24/72</u>	<u>11600</u>	<u>5</u>	
Mancos	<u>5150</u>	Remarks TA - 6/1/77 " to 6-30-80 " to 3-26-81 PBT 3100' 1-29-81 NITR A 1-29-81 pth. 2-2-81 10-7-80 1 Shelly O. Co.				<u>5/10/62</u>	<u>6490</u>	<u>20</u>	<u>8/22/73</u>	<u>15000</u>	<u>4</u>
Gallup	<u>6086</u>					<u>7/11/63</u>	<u>14150</u>	<u>12</u>	<u>6/74</u>	<u>S.I.</u>	
Dakota						<u>8/7/64</u>	<u>15454</u>	<u>11</u>	<u>6/75</u>	<u>S.I.</u>	
Morrison						<u>8/13/65</u>	<u>6000</u>	<u>16</u>	<u>6/76</u>	<u>S.I.</u>	
Entrada						<u>7/18/66</u>	<u>21428</u>	<u>7</u>	<u>6/77</u>	<u>S.I.</u>	
						<u>7/10/67</u>	<u>15250</u>	<u>8</u>	<u>6/78</u>	<u>S.I.</u>	
						<u>7/4/68</u>	<u>17857</u>	<u>7</u>	<u>7/79</u>	<u>S.I.</u>	
						<u>7/4/69</u>	<u>13100</u>	<u>10</u>	<u>8/80</u>	<u>S.I.</u>	

Otero Gat C. BA S 33 T 25N R 5W 11 H Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec. |
 Getty Oil Co. Jicarilla 'C' No. 22

Re-entry
 of well
 sold
 well p. 2.