

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
well well

2. NAME OF OPERATOR
El Paso Natural Gas Company

3. ADDRESS OF OPERATOR
P. O. Box 289, Farmington, N. M. 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1760'S, 1150'E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED
BUREAU OF LAND MANAGEMENT
FARMINGTON, N.M.

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
9/18-21, 1981

1. Run 1 1/4" tubing in hole and circulate.
2. Spot 10 sx cement plug on perforations. Displace 6 sx. (3552-3494')
3. Spot 10 sx cement plug 3319'-3219'.
4. Perforate 2 squeeze holes @ base Ojo Alamo 2830'-3060'. Spot 46 sx to cover Ojo Alamo 2830-3060. Displace 40 sx.
5. Perforate at 157' and spot 80 sx cement plug and squeeze leaving plug 157' to 57'.
6. Install P & A marker.

Spotted 8 sx cement surface plug.

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Production Engineer

DATE 10-2-87

(This space for Federal or State office use)

APPROVED BY

OR Bourman

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

"Complied with general requirements. Site ready for inspection.

Approved as to plugging of the well bore.

Liability under bond is retained until surface restoration is completed.

*See Instructions on Reverse Side

OPERATOR

5. LEASE
Contract No. 41
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Tribal
7. UNIT AGREEMENT NAME
Jicarilla Tribal
8. FARM OR LEASE NAME
Jicarilla D
9. WELL NO.
10
10. FIELD OR WILDCAT NAME
So. Blanco P.C.
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 30, T25N, R4W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
7249' DF

RECEIVED
APR 24 1987
OIL CON. DIV.
DIST. ?

APPROVED
AS AMENDED

DEC 11 1987

Robert J. Jones
M. MILLENBACH
AREA MANAGER