1. oil

well

2. NAME OF OPERATOR

gas

well

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

other

5. LEASE
Contract No. 41
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jigarilla Tribal
7. UNIT AGREEMENT NAME
Jicarilla Tribal
8. FARM OR LEASE NAME
Jicarilla D
9. WELL NO.
10
10. FIELD OR WILDCAT NAME
Blanco PC
11. SEC., T., R., M., OR BLK. AND SURVEY OF
AREA
Sec. 20. T-25-N. R-4-W
12. COUNTY OR PARISH 13. STATE
Rio Arriba NM
14. API NO
<u> </u>
1E ELEVATIONS (CHOW DE VOS AND WE

El Paso Natural Gas Co.

3. ADDRESS OF OPERATOR
P. O. Box 4289 Farmington, NM 87499-4289

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1760 S, 1150 E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

SUBSEQUENT REPORT OF:

15. ELEVATIONS (SHOW DF, KDB, AND WD)
7249 DF

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON\*
(other)

RECEIVED

(NOTE: Report results of multiple completion or zone

BUREAU OF E ...O .......GLMENT FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

## FINAL REPORT

Surface rehabilitation and reseeding have been completed. Location is ready for inspection.

ACCEPTED FOR RECORD

NOV 0 2 1983

FARMINGTON RESOURCE AREA

SIM

\*See Instructions on Reverse Side

CPERATOR