

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

April 23, 1965

Atlas Minerals, Inc.
2000 National Bank Building
Tulsa Oklahoma 74103

Attn: Mr. N. B. Gove

Dear Sir:

We have your letter of April 15, 1965 inquiring about the necessity of conducting a 1965 annual deliverability test on your #1 Bishop well located in Unit D, Section 25-25N-3W.

Wells in the Except Marginal classification do not require deliverability tests; however should further production history on the well result in a subsequent reclassification to Marginal or Non Marginal status a test would become necessary. Therefore I would advise you to take note of the well's continuing classification and act accordingly.

Yours very truly

Emery C. Arnold
Supervisor, Dist. #3

ECA:ks

VERBODEN TOEGANG TOT DEZE
DOCUMENTEN EN DE
INHOUD VAN DEZE