

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER SWD well

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface Unit C

RECEIVED

FEB 24 1986

14. PERMIT NO.
30-039-05861

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.

Contract No. 41

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla 30

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Lindrith Gallup Dakota West

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29-25N-4W

12. COUNTY OR PARISH

Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) sqz leak & acidize

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIKU, POOH w/ pkr on 1-31-86
- ② Set RBP @ 5305', test to 1000 psi. isolated leak between 3192'-3223'. Set pkr @ 3070'
- ③ Spot 24 bbls 15% HCL. Pumped 75 sxs Dowell 10-3 RFC cmt. Displaced cmt. Reversed out. Pressured up to 1000 psi
- ④ Rel pkr & POOH. Tag cmt and drill out. Press. test to 1000 psi. Leaked off 400 psi in 4 min. GIL w/ pkr, isolate leaks 3192'-3223'. Set pkr @ 3070'.
- ⑤ Spot acid to break down sqz. Pumped 150 sxs Dowell 10-4 RFC, flushed w/ bbls TFW. Pressured up to 1200 psi. Reversed out and WOC for 48 hrs.
- ⑥ Rel pkr & POOH. Drilled 90' cmt. Press. tested to 1000 psi, held OK. Circ. sand off RBP & POOH.
- ⑦ Set pkr @ 5323' and rig down on 2-13-86.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

2-21-86

(This space for Federal or State office use)

MAR 10 1986

RECEIVED FOR RECORD

APPROVED BY

TITLE

OIL CON. DIV.
DIST. 3

DATE

MAR 06 1986

CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

BY

E. J. J.

*See Instructions on Reverse Side

NMOCC

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Farmington(6) File