



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. SF 079601  
Unit Lydia Rents

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<u>Surface</u>	<u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING		
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR		
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT		
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY		
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 10, 1958

Well No. 5 is located 1190 ft. from S line and 990 ft. from E line of sec. 20

SE/4 Section 20  
( $\frac{1}{4}$  Sec. and Sec. No.)

25N  
(Twp.)

3E  
(Range)

N.M.P.M.  
(Meridian)

South Blanco FC Ext.  
(Field)

Rio Arriba  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 7360 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

SPUDDED: 8:00 A.M., 8/28/58.

Ran & set 10-3/4" casing at 226' & cemented w/200 sks. reg. cement, 2% CaCl.  
Cement circulated to surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Box 601

Address Terminado, New Mexico

By Richard B. ...

Title District Superintendent