

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

-- SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Conoco Inc.

3. Address and Telephone No.

10 Desta Drive STE 100W, Midland, TX 79705 (915)686-5424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FWL, SEC 20, T-25N, R- 4W, UNIT LTR 'K'

5. Lease Designation and Serial No.

CONTRACT 64

6. If Indian, Allottee or Tribe Name

JICARILLA APACHE

7. If Unit or CA, Agreement Designation

8. Well Name and No.

JICARILLA 20 #3

9. API Well No.

30-039-05915

10. Field and Pool, or Exploratory Area

LINDRITH GALLUP-DAKOTA, V

11. County or Parish, State

RIO ARriba, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-15-94 MIRU. POOH W/ 222 JTS 2 3/8" TEG. GIH W/ 5 1/2" CEMENT RETAINER SET @ 6460'. PRESSUER TEST TO 1500#. HELD GOOD. ESTABLISH INJECTION INTO GALLUP PERFS @ 1 bpm @ 500#. PLUG #1 76 SX CLASS B CMT. SQUEEZE 70 SX BELOW RETAINER & SPOT 6 SX ABOVE RETAINER TO 6458. PLUG #18 SX CLASS B CMT FROM 5024' TO 4864' PUH TO 4760' & SPOT 13 bbl 8.4# MUD TO 4220'. PLUG #3 17 SX CLASS B CMT FROM 4222' TO 4072'. PUH TO 3965' & SPOT 15 bbl 8.4 MUD UP TO 3334'. PERF 4 SQUEEZE HOLES @ 3334'. GIH W/ 5 1/2" CMT RETAINER SET @ 3278'. SQUEEZE 86 SX BELOW RETAINER & SPOT 29 SX ABOVE RETAINER TO 3070'. PUH. PERF 4 SQUEEZE HOLES @ 2922'. GIH W/ 5 1/2" CMT RETAINER SET @ 2879'. PLUG SQUEEZE 86 SX BELOW RETAINER. SPOT 24 SX LASS B CMT ON TOP OF RETAINER TO 2667'. PERF 2 SZUEEZE HOLES # 345'. ESTABLISH CIRC OUT BRADENHEAD. PLUG #6 119 SX CLASS B CMT FROM 345' TO SURFACE. CIRC 1 bbl GOOD CMT OUT BH. CUT OFF WELHEAD. INSTALL P&A MARKER W/ 30 SX CLASS B CMT. 6-18-94 BDMO. WELL IS PLUGGED.

14. I hereby certify that the foregoing is true and correct

Signed

Bill K. Zandley

Title

SR. REGULATORY SPEC

Date 7-14-94

(This space for Federal or State office use)

Approved by

Debby Lucero

Acting
Title

Chief, Lands and Mineral Resources

Date

AUG 29 1994