

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

RECEIVED
NOV 24 1992

OIL CON. DIV.
DIST. 3

2. Name of Operator
Meridian Oil Inc.

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
940' FNL, 1115' FWL Sec. 20, T-25-N, R-6-W, NMPM

5. Lease Number
SF-078882

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name
Canyon Largo Unit

8. Well Name & Number
Canyon Largo U #39

9. API Well No.
30-039-

10. Field and Pool
Ballard Pic. Cliffs

11. County and State
Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

11-11-92 MOL&RU. Blew down. ND WH. NU BOP. TOO H w/tbg. Set cmt ret @ 2228'. SDFN.

11-12-92 Cmt plug #1 w/112 sx under ret, displace w/7 BW, sting out, dump 8 sx on top of ret. TOO H 7 jts. Load hole. PT csg 600#, ok. TOO H. Perf 2 holes @ 2150'. Cmt plug #2 w/79 sx. TOO H to 1366'. Squeeze 38 sx behind csg. Locked up @ 600 psig. TOC @ 1800'. TOO H to 1250'. WOC. SDFN.

11-13-92 Tag TOC @ 1624'. Spot 32 bbl 9# 50 vis mud 1624-250'. TOO H LD. Perf 2 holes @ 250'. Est circ down csg & out bradenhead. Cmt plug #3 w/57 sx down csg & out bradenhead. Circ 0.5 bbl cmt returns. ND BOP. Cut off WH. Install dry hole marker w/10 sx. Released rig. Well plugged & abandoned.

14. I hereby certify that the foregoing is true and correct.

Signed *Peggy Brubaker* Title Regulatory Affairs Date 11/17/92

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

Approved as to plugging of the well bore.
Responsibility transferred to Federal Office
and the well owner is completed.

NMOCD

NOV 23 1992

AREA MANAGER