Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Convert to Injection

FORM APPROVED OMB No. 1004-0135

!	NM03991

SUNDRY NOTICES AND REPORTS ON WELLS	<u> </u>
Do not use this form for proposals to drill or to reenter an abandoned well. Use Form 3160-3 (APD) for such proposals N	**
abandoned well. Use Form 3160-3 (APD) for such proposate.	2002

Do not use th abandoned we	is form for proposals to dell. Use Form 3160-3 (APD)	orni or to recenter a) for such proposate	JN 2002	6. If India	n, Allottee or Tribe Name	
SUBMIT INTE	IPLICATE - Other Instru		side ()	7. If Unit	or CA/Agreement, Name and/or No	1.
1. Type of Well Oil Well Gas Well] Other			8. Well Name and No.		
2. Name of Operator NM&O Operating Company					Federal #10 9. API Well No.	
3a. Address 6 E. Fifth S	t, #200, Tulsa OK	3b. Phone No. (include 918-584-3		30-039-05956 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 826' FNL & 861' FWL NW/4 Sec. 24-T25N-R2W					y or Parish, State Arriba Co., NM	_
12. CHECK AI	PROPRIATE BOX(ES) TO	INDICATE NATU	RE OF NOTICE, RI	EPORT, C	OR OTHER DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION			
☐ Notice of Intent ☑ Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Start Reclamation Recomplete	/Resume)	Water Shut-Off Well Integrity Other	
	Change Plans	Plue and Abandon	Temporarily Ab	andon		

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

■ Water Disposal

3/23/02 - 5/23/02

Final Abandonment Notice

TIH to retrieve RBP. POH. RIH w/Howco G-6 packer and set @ 3370'. MIRU American Energy. Acidize Pictured Cliffs perforations w/1000 gal 7-1/2% FE acid at 3 BPM @ 900 psig. Flow back well. Unseat packer & TOH. TIH w/tubing assembly and land @ 3504'. NDBOP. NUWH. MI swabbing unit. Swab well to clean-up. MI well service unit. RIH w/rods & downhole pump. Set pumping unit and surface facilities. Start production operations on 5/23/02.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)							
Larry D. Sweet	e President						
Signature	Date 5/28/02						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by /s/ Patricia M. Hester	Lands and Mineral Resource Date JUN 6 2002						
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	int or lease Office						