OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

October 21, 1964

pt

Ameraia Fetreleum Corporation Box 1469 Durango, Colorado

Attn: Mr. D. F. Furse Foreman

> Re: Communication lest, #9 Jicarilla F, P-16-25N-5W

Dear Dan:

Either you have reversed the upper and lover zone pressures on the first section of this test or there is communication between the zones.

Please determine which conclusion is correct and if there is communication take immediate action to separate the producing zones.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

cc: OCC, Santa Fe, N. M.

OIL CONSERVATION GOMMISSION

SOUD FIF BRAZUG ROAD AZTEC, NEW MEX CE

100

en de la companya de la co La companya de la compan

ting a second filter of the second of the se

ing section of the se

1. 1. 1. 1.