

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

June 8, 1965

Amerada Petroleum Corporation
Box 1469
Durango, Colorado

Attn: Mr. D. F. Furse

Dear Mr. Furse:

1965

We have checked casing and tubing data on the/deliverability test which you recently submitted for your Jicarilla Apache "F" #9 well located in P-16-25N-5W and compared it with our records. We find the following discrepancies:

You indicate casing depth at 7360' on the test and our earlier records reflect 7439'. You show pay zone from 7276 to 7338 and our earlier records show 7140-7200.

Will you please check and let us know the correct information. In the event you find our earlier information is correct I would advise that you notify El Paso Natural Gas Company in order that the corrections may be made in their machine section in El Paso.

Yours very truly

Emery C. Arnold
Supervisor, District #3

ECA:ks

OIL CONSERVATION COMMISSION
1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO

June 1, 1966

Arizona Petroleum Association
P.O. Box 100
Phoenix, Arizona

Dear Mr. [Name]:

Thank you for your letter of May 11, 1966.

I have been unable to find any information on the subject of the well you mentioned. It is possible that the well is not in the records of the Arizona Petroleum Association. We will continue to search for it.

You indicated that the well was drilled in 1936. It is possible that the well was drilled in 1936, but it is not in the records of the Arizona Petroleum Association.

With your assistance, we will be able to know the well's location. In the event you find the well, please let us know. We will be glad to provide you with a copy of the well's record.

Sincerely,
[Name]

Very truly,
[Name]

cc: [Name]