NORTHWEST MEN MEXICO PACKER-LEAKAGE TEST

/UG = 5 - U =	KADA DESS (CORPORATION	ىلى	ease JlCari	lla Apache	<u>"F" No. 2</u>	
+							
of Well: Unit	tSec	· cwl	N Rg	e. Method	of Prod	Prod. Medium	
	Name of Reser	rvoir or Pool	, - ·			(Tbg. or Csg.)	
pper Completion Swer	Pictured C	liffs	Gas	Flow		Casing	
cmletion	Chacra	<u> </u>	Gas LOW SHUT-IN PR	Flow ESSURE DATA		Tubing	
prer Hour, d	ate	Length	of	SI pres	SS.	Stabilized?	
cmol Shut-	in 6/20/8	2 time shu	t-in 5 day	ys osig	270	(Yes or No) No	
Lower Hour, date Compl Shut-in 6/20/82		l Lenoth	Length of time shut-in 3 day		258	Stabilized? (Yes or No) No	
			FLOW TEST N		roducina (Unno	n on Towarle	
crimenced at (hour, date)* Time Lapsed time			sure	Zone producing (Upper or Lower): Prod. Zone			
hour, date)_			Lower Compl.		Ren	arks	
6/21	24	240	240				
6/22	48	245	250				
6/23	72	260	258				
€/24	96	265	120		Open Chacra		
6/25	120	270	120				
Ipper Hour, date [cmol Shut-in [cwer Hour, date [cmol Shut-in [cmenced at (hour, date)* [ine Lapsed time [hour, date) since **		MID-TEST SHUT-IN PRO Length of time shut-in Length of time shut-in FLOW TEST No. * Pressure Upper Compl. Lower Compl.		SI press. psig SI press. psig 2 Zone producing (Up:		Stabilized? (Yes or No) Stabilized? (Yes or No) er or Lower):	
-:-0	I ansed time	Pres	sure	Zone pr		r or Lower):	
-:	I ansed time	Pres	sure	Zone pr	Rem	r or Lower):	
Time	Lapsed time since **	Pres	Lower Compl.	Zone pr Prod. Zone Temp.	Rem	r or Lower): arks	
Time	Lapsed time since **	Pres	Lower Compl.	Zone pr Prod. Zone Temp.	Rem	r or Lower): arks	
roduction radics:	Lapsed time since ** te during te: BOPD be	Pres Upper Compl. st ased on MCFPD; Tested	Bbls. in thru (Orifice	Zone pr Prod. Zone Temp. Hrs. or Meter):	Rem.	r or Lower): arks GOR	
reduction radictions: EVARKS:	Lapsed time since ** te during temes BOPD because the since series to the since serie	Pres Upper Compl. st ased on MCFPD; Tested	Bbls. in thru (Orifice	Zone prod. Zone Temp. Hrs. or Meter):	Grav.	r or Lower): arks GOR the best of my	
Time hour, date) Toduction radia: ias: TMARKS: hereby cert mowledge.	te during temes that the	Pres Upper Compl. st ased on MCFPD; Tested	Bbls. in thru (Orifice	Zone pr Prod. Zone Temp. Hrs. or Meter):	Grav	r or Lower): arks GOR the best of my	
roduction radice: EMARKS: hereby cert cowledge. pproved: New Mexico O	te during temes that the	presupper Compl. stased on MCFPD; Tested information	Bbls. in thru (Orifice	Prod. Zone Prod. Zone Temp. Hrs. or Meter): d is true as or AMERAD Aux Hun	Grav	r or Lower): arks GOR COR COR COR COR COR COR COR	

- 1. A panier leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests small also be commenced on all multiple completion within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tuning have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- The packer leakage test shall commence when both zones of the dual
 completion are shutten for pressure stabilization. Both zones shall remain statin until the well-head pressure in each has stabilized, provided
 conever, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: If, on an initial packer learner test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Pollowing completion of Flow Test No. 1, the well shall again be shutin, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated muring Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain whithin while the zone which was previously shuthin is produced.

- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3-hour tests: inmediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.
- 24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test Form Revised 11-158, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test Form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the front of the Packer Leakage Test Form.

)	60	8	8	 	
			1		
			1		
			1 = = = = =		
				ii-i	
			-1		
			_		
			/		
<u> </u>					
h ====================================					
: :: ::::::::::::::::::::::::::::::::::			1		
;========					
			(J-		
			>, 1		
;=====================================			73		
·					

::				 	
					+++-
			= <u>=</u> ===+		