NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

		· · · · · · · · · · · · · · · · · · ·	OO MI	ron;		Lea	se (Jicari	lla Apa che "	F"	No. 2	
Cperator_	AMERAL	DA HESS COR	ORATI	252		_		Eid	Count	D-	o Arriba	
of Well:	Unit_	D_Sec1	Tw	p25N	[]	Rge.		ot had	Count	Pr	od. Medium	
-2		me of Reser			Tabe c	or Gas)	(Fl	OW OF	Art. Lift)	(Tb	g. or Csg.)	
Upper	T				Gas			Flow			oing .	
Lower	Completion Pictured Cliffs Lower Completion Chacra PRE-FI			Cas		Flow			Tul	oing		
Completion	n Clia			PRE-FI	1	-IN PRES	SSURE	DATA				
Spper Hour, date Length of				of SI p			I pre:	SS•	bilized? s or No) _{No}			
Compl Shut-in 4/24/83 tim			time shut-in 5 days				psig 200 SI press.			bilized?		
Le Lieum date			Length C	Length of time shut-in 3 days					(Ye	s or No) No		
Comp.J. S	nut-in	4/2403		O'LING DITE	FLOW	TEST NO.	.]			202 02	Towards	
Commenced	at (h	our, date)	-	Press					roducing (Up	ber or	LOWEL).	
Time	Time Lapsed time		Unner	Compl.	•	Prod. Zone Temp.			Remarks			
(hour, da	ce/		oppor									
4/25		24		210		10						
4/26		48		260	2	:60						
4/27		72		280	2	280						
4/28		96		190]	90			Open Chac	ra		
4/29		120		200	2	200						
4/29		120										
Productio	n rate	during tes	t					T.		l mare	GOB	
		DADD 1- 4		on	Bb (O	ls.in rifice 0	r Ne	ter):	orifice	.ra. • —	401	
Gas: 3	8		ACFPD;			T-IN PRE	SSUR	E DÁTĀ				
Upper Hou	ır, dat	ce		Length	of			SI pre	255•		abilized? es or No)	
Compl S	hut-ir	1		time shut-in				SI press.			abilized?	
	nower mours and			Length of time shut-in			psig			(Y	es or No)	
<u></u>					FLOW	TEST NO) <u>. 2</u>	Zone r	producing (II	mer o	r Lower):	
	Commenced at (hour, date)** Time Lapsed time Pres			Pres					e producing (Upper or Lower): one			
(hour, da	Time Lapsed time ur, date) since ** Up		Uppe:	er Compl. Lower		Compl. Temp.		Remarks		S		
<u> </u>												
			 									
			ļ								Email:	
						_		OIL CON. D				
			+						D	3 1. 0		
7 1 + 4		o duning to	et				L	 			0.07	
Production Oil.	on rat	BOPD b	ased	on	Bt	ols. in_		Hrs	•Gra	V •	GOH	
Gas:			_MCFP	D; Tested	d thru	(Orifice	or 1	deter)	•		GOR	
		,								+0 +1	he hest of my	
I hereby	certi	fy that the	info	rmation	harein :	containe	d is	true	wild combrace	יי ייי און	ne best of my	
knowledg		- 110							RADA HESS CO	KŁORA'I	ION	
Approved: 15 APPRove 19 New Mexico Oil Conservation Commission						By D. W. Helmis						
		Ret				Title		Pet	roleum Engin	eer		
		1001	<u>- 2 </u>			- -			17, 1983			
Title						Ja 66	····					

NORTHWEST NEW MEXICO PACKER LEAKINGS THST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order audiorizing the multiple completion. Such rests shall also be commenced on all multiple completions within seven days following recompletion and/or cheateal or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tublag have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Commission.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Commission in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided bowever, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test Shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: If, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- Following completion of Flow Test No. 1, the well shall again be shutin, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.

- 7. Pressures for gas-zone tests must be measured on each mose with a deadweight pressure gauge at time intervals as follows: Jahour tests: imadiately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day tests: immediately prior to the beginning of each flow period, at lesst one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.
- 24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges, the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Commission on Northwest New Mexico Packer Leakage Test form Revised 11-1-58, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and COR (oil zones only). A pressure versus time curve for each zone of each test shall be constructed on the reverse side of the Packer Leakage Test Form with all deadweight pressure points taken indicated thereon. For oil zones, the pressure curve should also indicate all key pressure changes which may be reflected by the recording gauge charts. These key pressure changes should also be tabulated on the front of the Packer Leakage Test Form.

	\$ \$	5 8 m			
<i>S</i> 2					
+					
2					
7					
,					
de					
		-V			
126					
		Q			
		8			
				<u> </u>	
ļ t					