

			X

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Sante Fe**
Lease No. **SF 079325**
Unit **A**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		Other	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

6 13 62

, 19

Well No. **Harvey Royal**
XX 5A1 is located **330** ft. from **[N]** line and **330** ft. from **[E]** line of sec. **5**
NENE **25N** **1E** **NMP** (Meridian)
(1/4 Sec. and Sec. No.) (Twp.) (Range)
Wildcat **Rio Arriba** (State or Territory)
(Field) (County or Subdivision)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 60', last 30' being in hard rock. Set 2 jts 7" and cemented by circulation to surface. Operations temporarily abandoned.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Francis L Harvey**
Wichita Falls, Texas
Address **(mail approved go to**
Shillander)

By **H E Shillander, Agent,**
Title **Box 1299, Albuquerque NM**