

Well File

P. O. Box 1809
Durango, Colorado 81301

September 28, 1971

United States Smelting Refining and Mining Company
19th Floor University Club Building
136 East South Temple
Salt Lake City, Utah 84111

Re: Floyd J. Ray No. 1 Bogey
SE $\frac{1}{4}$ SE $\frac{1}{4}$ sec. 33, T. 24 N., R. 4 W.
Rio Arriba County, New Mexico
Jicarilla Contract No. 70

Gentlemen:

You are the record lessee of the subject lease upon which the No. 1 Bogey well was drilled. Several requests of your designated operator, Floyd J. Ray, for a "Subsequent Report of Abandonment" on the well have not been answered. A request was also made of you, as lessee, on August 11, 1970, to see that the required report was filed. It has not yet been received by this office.

In order to avoid assessment of specific damages as provided for in CFR, Title 30, part 221.57 and 221.58 (1), six copies of a "Subsequent Report of Abandonment" (form 9-331) should be submitted to this office without further delay. The report should set forth a detailed account of the manner in which the well was plugged, including the location and extent of each plug set, the amount of casing left in the hole, and the date on which the plugging operation was performed.

Your cooperation in satisfying this lease obligation will be appreciated.

Sincerely yours,

(Orig. Sgd.) J. W. LONG

Jerry W. Long
District Engineer

Enclosure: 9-331 forms

cc:
NMOGCC-Aztec ✓



1. The first part of the report...


2. The second part of the report...

3. The third part of the report...

4. The fourth part of the report...

5. The fifth part of the report...

6. The sixth part of the report...



7. The seventh part of the report...

8. The eighth part of the report...