

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

FILED IN TRIPlicate
(If not, destruction of 1st
copy required)

Field Address
Report Number N. 42 10421
PLATE INFORMATION AND SERIAL NO.

SF 078883

SUNDREY NOTICES AND REPORTS ON WELLS

(Do not use this form for a report on a well or to design or plug back to a different reservoir.
See instructions on reverse side for each purpose.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	7. SETBACKMENT NAME Canyon Largo Unit
2. NAME OF OPERATOR El Paso Natural Gas Company	8. FARM OR LEASE NAME Canyon Largo Unit
3. ADDRESS OF OPERATOR PO Box 500, Harrington, NM 87401	9. WELL NO. 162
4. LOCATION OF WELL (Report on well location and in accordance with any State requirements. See instructions on reverse side.) At surface 1060'N, 500'E	10. FIELD AND TOWN, OR WELLS So. Blanco Pictured Cliffs
	11. SECTION, TOWNSHIP, OR RANGE AND SURVEY OR AREA Sec. 6, T-25-N, R-6-W NMPM
12. COUNTY OR PARISH 6476'GL	13. STATE Rio Arriba New Mexico.

16. Check Appropriate box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT ON:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) Abandon Chacra & Recomplete in Pictured Cliffs ☒ (NOTE: Report results of multiple completion or Recompletion Report on well completion or Recompletion Report on well location.)

17. DESCRIBE IN BRIEF OR ON A SEPARATE SHEET, IN CLARITY, all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.*


Due to low productivity it is planned to plug and abandon the Chacra formation and a complete in the Pictured Cliffs formation in this well as follows:

Squeeze perforation (3390-3410')(3492-3502') with 50 sacks cement, using a top wiper plug to displace cement 150' above top perforation.

Selectively perforate and sandwater fracture the Pictured Cliffs formation.



NOV 24 1971
U. S. GEOLOGICAL SURVEY
DURANGO, COLO



18. I hereby certify that the foregoing is true and correct

SIGNED HA Wood TITLE Petroleum Engineer DATE November 22, 1971

(This space for Federal or State office use)

APPROVED BY Am TITLE hold cited for PC plot DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side