UNITED STATES							
DEPARTMENT OF	THE	INTERIOR					
GEOLOGICAL	. SUF	RVEY					

NIERIUR	Contract 145
'EY	6. IF INDIAN, ALLOTTEE
	- Jicarilla 💆 🖟
	# A

S. LEASE

14. API NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)


1. oil well		gas weli	ES	other		
2. NAME OF OPERATOR						
South	ern i	Union	Ехр	lorations	Company	

- 3. ADDRESS OF OPERATOR
- P.O. Box 2179 Farmington, NM 87499
- 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 975' FSL & 1640' FEL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same
- 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Jicarilla K 9. WELL NO. 14 10. FIELD OR WILDCAT NAME Basin Dk, Otero Chacro, S Blanco PC 11. SEC., T., R., M., OR BLK. AND SURVEY OR **AREA** Sec 11-T25N-R5W N.M.P.M. 12. COUNTY OR PARISH 13. STATE Rio Arriba New Mexico

15. ELEVATIONS (SHOW DF, KDB, AND WD)

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

3 7 3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Pulled Dakota & Chacra Tubing. Replaced leaking tubing in both strings, redressed Packer & returned to production as before. Work was completed 10-20-82.

Subsurface Safety Valve: Manu. and Ty	Set @	Ft.	
18. thereby certify that the foregoing SIGNES SCALE OF OR	is true and correct	5/23/83	
-//	(This space for Federal or State office use)		
APPROVED BY	TITLE DATE _		

MAY 2" 1983

181