	1 9-331 - 1062\	UNITED STATES SUBMIT IN TRIPLICATE			Form approved Budget Bureau No. 42-R1424.		
(Mu)	DEPARTMENT OF THE			INTERIOF	(Other instructions or reverse side)	5. LEASE DESIGNATION	
	GEOLOGICAL SURVEY					147	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTE	
<u>ī.</u>						Jicarilla Apache 7. UNIT AGREEMENT NAME	
	OIL GAS WELL OTHER						
2.	NAME OF OPERATOR					8. FARM OR LEASE NAME	
	Continental Oil Company					AXI Apache "J"	
3.	DDRESS OF OPERATOR					9. WELL NO.	
	152 North Durbin, Casper, Wyoming 82601					20	
	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  NE NW 790 FNL, 1790 FWL (Unit Letter "C")				10. FIELD AND POOL, O	R WILDCAT	
					Otero Chacra 11. SEC., T., R., M., OR BLK. AND		
					nit Letter "C")	SURVEY OR AREA	L The state of the
					Sec. 5, T25	N, R5W	
14.	PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISE	
			6584 GR, 65	96' KB -	measuring point	Rio Arriba	New Mexico
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data						
						ENT REPORT OF:	
	TEST WATER SHUT-OFF	PULL OR ALTER CASING			WATER SHUT-OFF	REPAIRING	WELL
	FRACTURE TREAT	i	IULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING C	ASING
	SHOOT OR ACIDIZE		BANDON*		SHOOTING OR ACIDIZING	ABANDONME	
	REPAIR WELL	c	HANGE PLANS		(Other)	Casing Run s of multiple completion	an Well
	(Other) Completion or Recompl					letion Report and Log form.)	
17.	proposed work. If we nent to this work.) *	MPLETED OPE ell is direction	RATIONS (Clearly state nally drilled, give sub	all pertinent de surface locations	ctails, and give pertinent dates and measured and true vertic	, including estimated da al depths for all marker	te of starting any s and zones perti-
	Commenced drilling 10-26-71. 8 5/8" OD, 24# casing set at 239 sacks Class "A" with 2% CaCl <sub>2</sub> . Drilled to TD 5320 . Ran logs set at 5320' and cemented with 285 sacks "Liteweight" with 1/2 350 sacks 50-50 Pozmix "A" with 2% gel, 6 1/2#/sack Gilsonite a down at 8 a.m. 11-6-71. Released rig 11-7-71. WOC. Waiting oplete well.					. 5 $1/2$ " OD, of 1% CFR-2 f and $1/2$ of 1%	14# casing ollowed by CFR-2. Plug
						acrell.	TER