

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Dual Well P.C. & Gallup		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Apache 70
2. NAME OF OPERATOR Chace Oil Company, Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Apache
3. ADDRESS OF OPERATOR 313 Washington SE, Albuquerque, NM 87108		7. UNIT AGREEMENT NAME Jicarilla 70
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit C - 1080' FNL & 1590' FWL		8. FARM OR LEASE NAME Jicarilla 70
14. PERMIT NO.		9. WELL NO. 3
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6928 GR		10. FIELD AND POOL, OR WILDCAT Ballard
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 33 T24N R4W
		12. COUNTY OR PARISH 13. STATE Rio Arriba NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) Dual Completion <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8-10-76 Moved Rig in - pulled tubing - Set Bridge plug at 5800' - Ran Bond log. Perforated Pictured Cliffs formation from 2700' - 2710'.

8-11-76 Fractured P.C. with 15,000# 10-20 sd and 15000 gal of slick water. Well went on Vacuum.

8-12-76 Opened well-Ran 2705' of 2 3/8" tbg. Started swabbing - Well making gas, water and sand. Pumped sand out of well. Flowed gas and water.

8-13-76 Flowing gas and water - water decreasing.

8-14 to 8-17-76 Put well on meter and separator - Well potentialled 64 McF PD.

8-18-76 Pulled tubing-drilled out Bridge Plug-Went in with tubing and packer-Tubing set at 6128'- packer set at 2900'.

8-19-76 Opened well up - placed back on production.

8-21-76 Shut in 2 weeks for packer test - packer leaking.

9-8-76 Producing with packer leaking some.

3-9-77 Hearing set for 4-26-77 to comingle

4-26-77 State Commission granted permission to comingle P.C. and Gallup-Dakota. Gas Production to be 75% Pictured Cliffs and 25% Gallup-Dakota.

18. I hereby certify that the foregoing is true and correct

SIGNED Rayce McCarty TITLE President

DATE 7-11-77

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____