## UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR  GEOLOGICAL SURVEY	NM 03556 : -  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1. oil gas other	9. WELL NO. 224-24
2. NAME OF OPERATOR	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Felix J. Hickman  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME   TO SEE   Blanco M.V., Ojito Gallup - Dakota
P.O. Box 12307, El Paso, Texas 79912	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA / T25N, R3W 를 포함되는
AT SURFACE: 1850' FNL and 790' FWL AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE Rio Arriba. New Mexico
AT TOTAL DEPTH: same	14. API NO. 3 3 3 3 5 8 5
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 7298 K.B.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7290 N.B.:
FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  TEST WATER SHUT-OFF  RECEL  REPAIR WELL	VED Control of the co
PULL OR ALTER CASING   Output  Output	(NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE []	이 얼룩되고 가 화물싫은 그것
ABANDON* U. S. GEOLOGIC FARMINGTON	AL SURVEY
(other) FARMINGTON	N. N. Miller Brown and State of the second s
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Set production packer at 6250'. Perforate	firectionally drilled, give subsurface locations and nt to this work.)*
49 holes. Fracture interval with 90,000 ga 20-40 sand. Ran production tubing for Dako packer at 6250'. Ran 2 1/16" production tu	llons water and 100,000#;
at 5993'.	The relation of the control of the c
	resaj gratimatus not be ma i bias val torskat ni mutisaci sistematica i dinarismipsi istališ sida dinarismipsi istališ sida dinarismipsi istalismisi dinarismisi istalismisi sistematica interiorismisi cat to dinarismisi istalismisi cat to dinarismisi istalismisi cat to dinarismisi istalismisi
<u>.</u>	
	gretimentia not be mis wal local to 1 th one can extremine it has to 2 th one can be missed and discount and another than bloods after the can be missed and the missed and the missed and the can be missed and the mis
	Section 1997
Subsurface Safety Valve: Manu. and Type	Set @ = 1 = 5 = Ft.
18. I hereby certify that the foregoing is true and correct	
Agent Agent	October 11, 1982
(This space for Federal or State of	
	ଗ୍ଟିମିବ୍ଟି ମୂଲି ଗ୍ରିକି
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
	10 PRESENTATION OF STREET
	- 19 1

\*See Instructions on Reverse Side

00 1 382