ENERGY AND MINERALS DEPARTMENT 3 NMOCD	I McHugh
OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78
FILE U.S.G.S. LAND OFFICE OPERATOR	State State Oil 6 Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS [DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECREN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
I. OIL GAS XX OTHER-	8. Farm or Lease Name -
2. Name of Sperator Jenome P. McHugh 3. Address of Sperator	Mother Lode 9. Well No.
P O Box 208, Farmington, NM 87499	10. Field and Pool, or Wildcat
UNIT LETTER H 1730 FEET FROM THE North LINE AND 860 FEET FROM	Basin Dakota
THELINE, SECTION TOWNSHIP RANGE NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 7321 GL; 7333 RKB	12. County Rio Arriba
16. Check Appropriate Box To Indicate Nature of Notice, Report or Otl	
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB OTHER PBTD & Perforation	ALTERING CASING PLUG AND ABANDONMENT
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	
7-9-83 Rig up Western Co. Pressure test to 4000 psi; okay. 7½% H.C.L. P.O.H. Rig up Basin Perforators. Ran GR 3.771" O.D. Gauge Ring from PBTD 8152" to 7700', 7100 5850-5100'. Perforate Dakota formation with 3-1/8" g 7861, 72, 77, 80½, 92, 7905, 14, 37, 60, 66, 72,74, 7 90, 8045, 48, 51, 8100, 08, Total 22 holes (0.34"). formation with 2800 psi. Drop 33 RCN ball sealers. Ball off with 4000 psi. Ran 4½" junk basket. Recove (20 hits). Shut down.	-CCI with to 6700', un as follows: 6, 80, 82, 84, Break down Gool ball action. ered 22 balls
OIL COI	N. DIV. T. 3
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Agent	DATE
Jim L. Jacobs	90 L
APPROVED BY	DATE