
Form 3160 (Novem of 1983) (Cornerly 9=331)	UNITED STATES DEPARTMENT OF THE INT BUREAU OF LAND MANAGEM		5 LEASE DESIGNATION AND SERIAL NO.  JICACI La Contract	- 147
ffo not use this	IDRY NOTICES AND REPORT form for proposals to drill or to deepen or p Use "APPLICATION FOR PERMIT—" for st	lug back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	<u> </u>
OIL GAR WELL WELL	X OTHER		7. UNIT AGREEMENT NAME	
Amoco Production Co.			8. PARM OR LEASE NAME  Jicarilla Contract	- <del>14</del> 7
3. ADDRESS OF OFFERATOR 501 Airport Drive, Farmington, N M 87401			9. WBLL HO. 9E	_
4. LOCATION OF WELL (R See also space 17 belo At surface	eport location clearly and in accordance with	Tos gratel tedaltemante.	10. FIELD AND POOL, OR WILDCAT Undes. Gallup/Basin	- Dak
910' FSL X		MAR 10 1985	11. SEC. T. R., M., OR BLE. AND SURVEY OR AREA SW/SE Sec. 7 T25N,	_
14. PERMIT NO	BUREA 15. ELEVATIONS (Show WHEM) 6664 G	U OF LAND MANAGER AREA PROF. AT. CK. etc.)	12. COUNTY OR PARISH 13. STATE Rio Arriba N.M.	_
6.	Check Appropriate Box To Indicat		Other Data	_
TENT WATER SHUT-OF FRACTORF TREAT MODEL OR ACTOIZE ESPAIR WEST, 1945/2. Status	MULTIPLE COMPLETE  ABANDON*  CHANGE PLANS	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING OR ACIDIZING  (Other)  (NOTE: Report results	ALTERING WELL  ALTERING CASING  ABANDONMENT*  of multiple completion on Well lettor Report and Log form.)	
proposed work. If nent to this work.) *	COMPLETED OPERATIONS (Clearly state all pert) well is directionally drilled, give subsurface	nent details and give testingst dates	including authorized data ad accept	- \$ 1-

The recorded pressures for the Gallup formation for the month of March 1985 are as follows:

Tubing Pressure 220 psi (shut-in) Casing Pressure 900 psi (shut-in)



(This apace for Federal or State office use)	TITLE Adm. Supervisor	DAACCEPVED FOR RECORD	
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	FARMINGION RESOURCE AREA	
*See Instructions on Reverse Side		BY	