



## Southland Royalty Company

January 8, 1985

Oil Conservation Division  
1000 Rio Brazos Road  
Aztec, New Mexico 87410

Gentlemen:

The following is the deviation record for Southland Royalty Company's Hawk Federal #3 well located in Section 35, T25N, R2W, Rio Arriba, New Mexico.

<u>Depth</u>	<u>Deviation</u>	<u>Depth</u>	<u>Deviation</u>
415'	3/4 deg.	3940'	1/2 deg.
848'	1-1/2 deg.	4506'	1/2 deg.
1351'	1-1/2 deg.	4700'	1/2 deg.
1918'	2-1/4 deg.	5199'	1/2 deg.
2138'	2-1/2 deg.	5627'	1 deg.
2335'	2 deg.	6142'	1-1/4 deg.
2798'	1-1/4 deg.	6645'	1-1/4 deg.
3230'	2 deg.	7140'	1/2 deg.
3427'	1-1/2 deg.	7650'	1/4 deg.
		7900'	1/4 deg.

Sincerely,

SOUTHLAND ROYALTY COMPANY

R. E. Fielder  
District Production Manager

REF/eg

Attachment

REC-1  
JAN 09 1985  
OIL CON. DIV.  
DIST. 3

Oil Conservation Division  
Page Two  
January 8, 1985




STATE OF NEW MEXICO

County of San Juan

The foregoing instrument was acknowledged before me this 8th day of January, 1985,  
by R. E. Fielder of Southland Royalty Company on behalf of said Company.

NOTARY BOND FILED WITH SECRETARY OF STATE

My Commission Expires: 4-27-85

  
\_\_\_\_\_  
Esther J. Greyeyes  
Notary Public - NM