(Ne	omerly 9331) DE	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			SUBMIT IN TRIPLICAT (Other Instructions on verse side)	ro-	Budge Burgen No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.		
	SUNDRY (Do not use this form Use	Y NOTE	CES AND RE	PORTS ON pen or plug back t	WELLS o a different reservoir.		G. IF INDIAN, ALLOTTEE OR TRIBE NAM	ė.	
1.	OIL [7] GAB [7]						7. UNIT AGREEMENT NAME		
WELL WELL OTHER  2. NAME OF OPERATOR							N/A		
۷.							8. FARM OF LEASE NAME		
3	Mallon Oil Company 3. ADDRESS OF OPERATOR						Ribeyowids-Federal "2"		
٠.									
1099 18th St., Ste. 2750, Denver, CO 80202  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface  860' FSL & 990' FEL (SE/4, SE/4)						G	16 O. FIELD AND POOL, OR WILDCAT Gavilan Mancos, Gavilan-		
							reenhorn-Craneros-Dako 11. BEC, T, E, W., OR BLE. AND BURVEY OR AREA		
							Sec. 2, T25N, R2W		
19.	PERMIT NO.		15. ELEVATIONS (Sho	w whether DF, RT, C	R, etc.)		12. COUNTY OR PARISH 13. STATE	_	
			7444' KB,	7432 GL			Rio Arriba NM		
16.	Check Appropriate Box To Indicate Nature of Netter D					0.1		-	
	Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data								
					SUBSEQUENT REPORT OF:				
	TEST WATER SHUT-OFF	1	LL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL		
	FRACTURE TREAT		LTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING		
	RHOOT OR ACIDIZE REPAIR WELL		ANDON*		SHOOTING OR ACIDIZING		ABANDONMENT*		
	(Other) Commingle		LANGE PLANS	\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.	(Other)				
 17.	SCRIDE PROPOSED OF COMPLETON OF Recomplet					apreci	of multiple completion on Well tion Report and Log form.)		
	escribe proposed on completed operations (Clearly state all pertinent details, and give pertinent dates, in nent to this work.) well is directionally drilled, give subsurface locations and measured and true vertical ince 4/26/91 the subject well has produced the Dakota Ss. A pacet at 7716' to isolate the Dakota perforations (775, 2, 571).						vor an markets und fones bell	Г-	
]	producing Mancos Dakota since shor Dump is occurring are requesting act to test the Dakot The Mancos produc	perforantly aforantly aforantly aforantly aforantly and, attion we	ations (6784- ter:beginning ng a:reliable tative appro- if:necessary	-7618'). T g production e test of to val to common apply for	he eratic product n indicates that	rom tion gas ial for glin	the previously nates from the solocking in the impossible. We a time sufficient ng of the zones.		

TITLE Production Manager DATE July 15, 1991

\*See Instructions on Reverse Side

TITLE

SIGNED Joe H.

APPROVED BY

(This space for Federal or State office use)

CONDITIONS OF APPROVAL, IF ANY: