Submit 3 Copies to Appropriate

State of New Mexico Form C-103 Energy, Minerals and Natural Resources Department Revised 1-1-89 District Office OIL CONSERVATION DIVISION DISTRICT WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe. New Mexico 87504-2088 5. Indicate Type of Lease FEE X STATE 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" Clayton S. Schmidt and/or (FORM C-101) FOR SUCH PROPOSALS.) Patricia M. Schmidt Type of Well: WTIL X OTHER 2. Name of Operator 8. Well No. Cido # 6 Bus-Rx, Inc. 9. Pool name or Wildcat 3. Address of Operator East Puerto Chiquito Mancos Tucson, AZ 85740 P.O. Box 35938 4. Well Location Feet From The South 525 East Feet From The Line NMPM Rio Arriba SectionNE of SE of Sec Township 25 N Range 1 E County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 7139 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK **ALTERING CASING** PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Dry Hole OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed Cido #6 has been plugged and abandoned as follows by Trend, Inc.: 11/5/85 - Run Tbg. to 2654.88 Set cement plug from 2654.88 to 2479.09, pulled up to 2000' shutdown. 11/6/85 - Run Tbg. to tag cement. But no fill mixed a mother 10SX plug and set it from 2654.88 to 2518.78, pulled up 300' and waited 4 hrs. and tagged cement at 2535 pull Tbg and perforated cas. at 1890 R.IH with Tbg to 1890.39' mixed cement and pumped plug from 1890.89' to 1755.85' pulled Tbg and shut down. 11/7/85 - Run Tbg to 1764' tag T.O.C. pulled Tbg and perforated 1213 R.I.H. with Tbg. T.O.C. at 1113' pull Tbg. and perforated at 164'. R.I.H. with Tbg and mixed cement and pumped to surface. Used a total of 75 SX cement on job .1ANT 2 1989

CON. DIV. in true anti-complete to the best of my knowledge and belief. I hereby certify that the information above DIST. 3 DATE 1/10/89 President SIGNATURE _ TELEPHONE NO602-623-2211 A. M. Kalaf TYPE OR PRINT NAME

DEFUTY OIL & GAS INSPECTOR, DIST. #3 (This space for State Use)

Original Signed by CHARLES GHOLSOM

APTROVED BY