Form 3160-5 (June 1993)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED			
Budget Bureau	No.	1004-013:	
C			

Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS NM-04075 Do not use this form for proposals to drill or to deepen a fileentry to a different reservoir. 5. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposate N.M. 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE Type of Well Oil X Gas 8. Well Name and No. Well 2. Name of Operator Arco Hill 23 #1 Taurus Exploration, U.S.A., Inc. 3. Address and Telephone No. 9. API Well No. 2198 Bloomfield Highway: Farmington, NM 87401 <u>30-039-24049</u> 10. Field and Pool, or exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) West Lindrith Gallup-Dakota 1810' FNL, 345'' FEL. Sec. 28. T25N, R3W, NMPM 11. County or Parish, State Rio Arriba NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent X Abandonment Change of Plans Recompletion New Construction Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection Other Dispose Water (Note: Report results of multiple completion on Well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Notified Cuba BLM on 3/18/98 3/19/98 POOH with 254 jts. 2 7/8" tubing, attempt to run 5 1/2" cement retairer. 3/20/98 Attempt to run 5 1/2" casing scraper, stacked out at 195'. Standard 5 1/2" CR would not run in 5 1/2" 23-26# casing. procedure change approved by Al Yepa with BLM. RIH with 2 7/8" tubing tag up at 8114'. Plug #1 with 110 sx Class B cement from 8114' to 6904' to cover Dakota and fill Gallup perforations. WOC. 3/23/98 Tag cement at 6780'. Load with water and pressure test to 500#, held ok.

Plug #2 with 15 sx Class B cement inside casing from 5437' to 5296' to cover Mesaverde top. Plug #3 with 15 sx Class B cement inside casing from 3757' to 3614' to cover Pictured Cliffs top. Perforate 3 squeeze holes at 3620'. Set 5 1/2" wireline retainer at 3562'. 3/24/98 Pump into squeeze hole 2 BPM at 250#. Plug #4 with retainer at 3562'. Mix 99 sx Class B cement, squeeze 70 sx outside 5 1/2" casing from 3620' to 3382' and leave 29 sx inside casing to 3332' to cover 0jo Alamo top. Perforate 3 squeeze holes at 1803'. Set 5 1/2" retainer at 1759'. Pumped into squeeze holes 1 1/2 BPM at 800#. Plug #5 with retainer at 1759', mix 45 sx Class B cement and squeeze 8 sx outside 5 1/2" casing then pressured to 1800#, sting out of retainer and spot 37 sx inside casing up to 1319'. Perforate 3 squeeze holes at 821'. Plug #6 with tubing at 807', mix 50 sx Class B cement, squeeze 15 sx outside 5 1/2" casing to cover 8.5/8" shoe and leave 13.5 sx inside casing at 621'. WOC. 3/25/98 Tag cement at 569'. Perforate 3.5/98squeeze holes at 50'. Plug #7 with 28 sx Class B cement from 50' to surface, circulate 1/2 bbl good cement out bradenhead. WOC. Cut off wellhead, found cement down 20' in 5 1/2" and at surface

4. I hereby certify that the foregoing is true and correct		d de sui race (over)
14. I hereby certify that the foregoing is true and correct Signed	Title Production Foreman	Date 4/16/98
(This space for Federal or State office use) Approved by Conditions of approval, if any:	Lands and Mineral Resources	- Dato

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements