

6 BLM, Fmn 1 Navajo Nation 1 File

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE	N00-C-14-20-4311
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	Navajo Allotted
7. UNIT AGREEMENT NAME	
8. FARM OR LEASE NAME	Bumble
9. WELL NO.	1
10. FIELD OR WILDCAT NAME	Cuervo Mesaverde
11. SEC., T., R., M. OR BLK. AND SURVEY OR AREA	Sec. 27, T24N, R8W, NMPM
12. COUNTY OR PARISH	San Juan
13. STATE	NM
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD)	6767' RKB

1. oil well ☐ gas well ☐ other ☐ Dry Hole

2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL - 660' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED

(NOTE: Report results of multiple completion or change on Form 9-330)

RECEIVED
JAN 17 1985
OIL CON. DIV.
DISP. DIV.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and include pertinent data including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abanded this well on 10-30-84 as follows:

1. Squeezed perfs 4117-4129' with 5 sx cement.
2. Spotted cement plug 4117-4065' (6 sx).
3. Spotted cement plug 2590-2487' (12 sx).
4. Spotted cement plug 1810-1707' (12 sx).
5. Spotted cement plug 1165-941' (26 sx).
6. Installed dry hole marker.

Approved as to plugging of the well bore.
Liability under bond is retained until surface restoration is completed.

9.0#/gal. mud spotted between plugs.

Work completed 10-30-84. Will restore surface and seed location at a later date.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED Jim L. Jacobs TITLE Geologist DATE 10-31-84

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

NOV 01 1984
M. MILLENBACH
AREA MANAGER

NMOCC