	/
UNITED STATES SUBMIT IN TRIPLICA (Other Instructions of DEPARTMENT OF THE INTERIOR verse side) GEOLOGICAL SURVEY	5. LEASE DESIGNATION AND SERIAL NO. NM-0557389
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL OF GAS OTHER	7. UNIT AGREEMENT NAME  X  S. FARM OR LEASE NAME
2. NAME OF OPERATOR  Harry L. Bigbee  3. ADDRESS OF OPERATOR	Nancy 9. WELL NO.
P.O. Box 669, Santa Fe, N.M. 87501  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*	# 3 10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface  990 FSL and 1793 FWL	Wildcat 11. SEC, T., R., M., OR BLK. AND SURVEY OR AREA
Sec.12 TWP 24N Rge 8V  14. PERMIT NO.  15. ELEVATIONS (Show whether DF, BT, GR, etc.)  G.L. 7202	12. COUNTY OR PARISH 13. STATE
16. Check Appropriate Box To Indicate Nature of Notice, Report,	or Other Data
(Other) Completion or R	results of multiple completion on Weil ecompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent proposed work. If well is directionally drilled, give subsurface locations and measured and true nent to this work.)*  Set packer at 6845, Spotted 500 gallons 15% acid.  6806 68086812 6815 to 6831. Oil sand frage of 20-40 sand and 44,060 gallons of cil. Spear he	Perforated 6804 to acked with 25,000 lbs.
28% HCL acid. Set plug at 6100 perforated and at	The state of the s
sand fracked with 1,000 acide $15\%$ . 15,000 lbs of $t$ of water. Drilled plugs at 6100 and at 6845. Swabbe	
on pump.  REC  OCT 1 6 1968  OCT	EIVED 1 5 1968 LOGICAL, SU
18. I hereby certify that the foregoing is true and correct	Oct.11.1968

\*See Instructions on Reverse Side

DATE \_\_\_

(This space for Federal or State office use)