


(SUBMIT IN TRIPLICATE)

Land Office Santa Fe  
Lease No. 080167  
Unit \_\_\_\_\_

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 6, 1956

Elliott

Well No. 1-B is located 2010 ft. from ~~XX~~ S line and 660 ft. from ~~XX~~ E line of sec. 1


C NE SE Sec. 1      24 N.      11 W      6th P. M.  
( $\frac{1}{4}$  Sec. and Sec. No.)      (Twp.)      (Range)      (Meridian)  
Wildcat      San Juan      New Mexico  
(Field)      (County or Subdivision)      (State or Territory)

The elevation of the derrick floor above sea level is 6719.3 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Intend to set plugs for abandonment, core analysis and Schlumberger show very poor chances for oil. T.D. 5191. Intend to set plugs are these depths. 4950 to 5100 with 40 sacks; 3950 to 4050 with 35 sacks; 1700 to 1800 with 35 sacks; 1350 to 1500 with 30 sacks; 0 to 10 with 5 sacks; Erecting regulation marker in top of 10-3/4. Heavy viscosity mud spotted between cement plugs. Will clean location and backfill pits.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company C.M.&W. Drilling Company

Address 1340 South Santa Fe Drive

Denver 23, Colorado

By L. J. Overton (signed)  
L. J. Overton,  
Title Drilling Superintendent

