

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

ST 073554

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Skelly Oil Company

3. ADDRESS OF OPERATOR

1960 Lincoln Street, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' FSL and 1930' FEL Section 3-24N-10W

7. UNIT AGREEMENT NAME

East Bisti Unit

8. FARM OR LEASE NAME

9. WELL NO.

94

10. FIELD AND POOL, OR WILDCAT

Bisti Lower Galla

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Section 3-24N-10W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6872' GR 6882' KB

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

All depths shown are from ground level.

7-1-71 MI & RU Aztec Well Service Unit. Pulled rods.

Spotted cement plug from 5430' to 5339'. Pulled 2" tubing.

Pulled and worked 5-1/2" casing to free same. Rigged up blue jet, perforated from 1784' to 1735' w/4 shots. Ran 2" tubing and spotted cement plug from 1735' to 1635'.

Pulled 2" tubing. Shot casing at 1343'. Spotted cement plug from 1393' to 1293', 50' inside 5-1/2" casing and 50' above 5-1/2" casing stub.

Pulled casing spotted cement plug from 1040' to 940'. Pulled 5-1/2" casing.

Spotted 10' cement plug in surface casing. Installed dry hole marker.

Completed P & A 7-14-71.

18. I hereby certify that the foregoing is true and correct

SIGNED

L. L. Buhl

TITLE

Lead Clerk

DATE

10-19-71

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

