

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other Instructions
on reverse side)

DATE

Form approved
Budget Bureau No. 42-R1424.

2. LEASE DESIGNATION AND SERIAL NO.

N00-C-14-20-5314

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Newcomb Navajo

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Dakota 'D'

11. SEC. T. R. M. OR DLG. AND
SURVEY OR AREA

Sec. 14, T24N R17W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

Tesoro Petroleum Corporation

3. ADDRESS OF OPERATOR

1776 Lincoln St., Suite 1012, Denver, Colorado 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

790' FNL and 900' FEL NE/4 NE/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

GR 5446'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:



WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well drilled to the Dakota 'D' zone was incapable of producing at a commercial oil or gas rate from any of the porous zones penetrated. Tesoro plugged and abandoned this well according to the following procedure:

1. 67 sx. class 'A' cement from 4000' to 4200'.
2. 67 sx. class 'A' cement from 3300' to 3500'.
3. 67 sx. class 'A' cement from 2000' to 2200'.
4. 15 sx. class 'A' cement at surface.
5. A dry hole marker was installed as required by state regulations.
6. Location will be cleaned and restored to the original condition and should be ready for inspection by January 1, 1975.



18. I hereby certify that the foregoing is true and correct

SIGNED

L.C. Marquardt

TITLE

District Engineer

DATE

10/18/74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE