5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

Dec. 1973

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	NM 8909 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
reservoir. Use Form 9–331–C for such proposals.)	Gee, I
1. oil gas well x other	9. WELL NO. #3
2. NAME OF OPERATOR Dugan Production Corp.	10. FIELD OR WILDCAT NAME
3. ADDRESS CF OPERATOR Box 234, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) 990' FNL - 940' FEL	Sec 12 T24N R9W
AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6766' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT	••• :
SHOOT OR ACIDIZE REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	\cdot
ABANDON*	
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stating including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertined. Pluggec and abandoned well as follows: 5-30-78: Spotted cement plug from 1900 - 1770 	ent to this work.)*
 Shot csg @ 860', spotted 35 sx plug over spotted 21 sx plug from surface 	r stub, pulled csg to 100',
3. June 14, 1979 - erected dry hole marker	and cleaned location.
Subsurface Safety Valve: Manu. and Type 18. I hereby cartify that the following is true and correct	Set @Ft.
President	7-30-79
Thomas A. Dugan (This space for Federal or State	office use)
APPROVED BY TITLE TOTAL TITLE	DATE
Conditions of the control of	

*See Instructions on Reverse Side

nunocc