

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-1408

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

EXICO

8. FARM OR LEASE NAME

Blanco Wash

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Undesignated FD

11. SEC., T., R., W., OR BLK. AND
SURVEY OR AREA

Sec. 11, T24N, R9W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR

P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1450' FNL - 860' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6622' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged back and a completion attempted in the Pictured Cliffs - Fruitland which was not successful. We now plan to plug and abandon the well as follows:

1. Spot cement plug over P.C. Fruitland perfs to 1620'.
2. Spot 10 sx cement plug at surface.
3. Install dry hole marker and abandon well.

RECEIVED

FEB 13 1988

OIL CON. DIV.

OFF. 9

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE

Geologist

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

FEB 28 1988

AREA MANAGER

BUREAU OF LAND MANAGEMENT
Caller Service 4104
Farmington, New Mexico 87499

Attachment to Notice of
Intention to Abandon

Re: Permanent Abandonment

Well: 7 Blanco Wash

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."

2. Bill Blackwell with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 325-4572.

3. Blowout prevention equipment is required.

4. The following modifications to your plugging program are to be made (when applicable):

Bring plug up to 1400' to cover Fruitland (top @ 1458')
Spot cement plug from 1143'-800' Ojo Alamo (Top @ 850', base @ 1093')
" " " " 264-164' Surface casing shoe

Office Hours: 7:45 A.M. to 4:30 P.M.