Form 3160-5 (November 1994)

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM A	PPRQ√ED
OMB No. Expires Ju	
Expires Ju	ily∕31, 1996

			•	
				_
5.	Lease	Serial	No.	1

Date

NM-20305

6. If	Indian.	Allottee	or Tribe	Name
-------	---------	----------	----------	------

				7. If Unit or CA/Agreer	nent, Name and/or No.	
SUBMIT IN TRIPL	ICATE - Other instru	ictions on revers	e side			
1. Type of Well		198	12/22			
X Oil Well Gas Well	Other	EL 10		8. Well Name and No.		
2. Name of Operator		(S) FED	2001	Federal 34 No. 43	3	
Elm Ridge Resources, Inc.		FED TED	EVED 2	9. API Well No.		
3a. Address		3b. Phone No. include	ATRY 1914	30-045-24521		
PO Box 189, Farmington, NM	87499	505-632-3478	ர்.3	10. Field and Pool, or Ex	cploratory Area	
4. Location of Well (Footage, Sec., T., R		(8/03/61)		Lybrook Gallup 11. County or Parish, State		
1760' FSL& 940' FEL. Sec. 34	4-T24N - R8W					
		9	A LAVACE	Oan tuan		
				San Juan		
12. CHECK APPROPRIATE BOX(E	ES) TO INDICATE NATURE	OF NOTICE, REPORT	T, OR OTHER DA	ATA		
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	Deepen	☐ Production	(Start/Resume)	Water Shut-Off	
Notice of litterit	Alter Casing	Fracture Treat	Reclamatio	` =	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	, <u> </u>	Other	
Dansequent report	Change Plans	Plug and Abandon	Temporaril	y Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osal		
13. Describe Proposed or Completed Operat If the proposal is to deepen directionall Attach the Bond under which the work Pollowing completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspection. EIM Ridge Resources propose Well Service. MISU - RU - Ni hole. Set BP @ +/- 5000'. Sp including 50% excess from +/- 1580'. Pull up spot 20 sxs (23 Squeeze 160 sxs 188.8 ft ³ . C	y or recomplete horizontally, give will be performed or provide the perations. If the operation results is pandonment Notices shall be filed ection.) es the following operation ipple down wellhead. Nipple down wellhead. Nipple toot 100' cement plug 12 -3286 to +/- 3186. Pull (8.6ft ³) including 50% exceptions.	subsurface locations and me Bond No. on file with BLI in a multiple completion or only after all requirements, ns to plug & abando pple up BOP. Pull to sxs (14.16ft ³) including up spot 25 sxs (29.5 cess from +/- 1166 to	with the Federal ubing and rods thing 50% exces of the first thing 50% exces of the first thing thing the first thing thing the first thing the first thing thing the first th	car agous of an perment liber of the interval, a Form 3160-4 and 34-43 to be perform as. Pickup CIBP and ss. Pull up spot 12 50% excess from + 1 out perforate guid	hed within 30 days shall be filed once d the operator has need by Triple P d workstring - run in sxs; (14.16ft ³)	
14. I hereby certify that the foregoing is t	true and correct				. <u></u>	
Name (Printed/Typed)		Title	Produ	uction Assistant	.;; .;J	
	Grubelnik	Date		2000117 toolotaire	- W	
Signature	Ali boloni) Date	Dece	mber 21, 2000		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Approved by

THIS SPACE FOR FEDERAL OR STATE USE

Title