

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

RECEIVED
JUL 11 1994

OIL CON. DIV.
DIST. 3

1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

COLEMAN OIL AND GAS INC.

3. Address and Telephone No.

P.O. DRAWER 3337, FARMINGTON, NM 87499 (505) 327-0356

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC 6, T24N, R10W

800'N 890'E

5. Lease Designation and Serial No.
NOOC-14-20-3588

6. If Indian, Allottee or Tribe Name

JOE WHITE

7. If Unit or CA, Agreement Designation

8. Well Name and No.

NAVAJO WOOD

9. API Well No.

1

10. Field and Pool, or Exploratory Area

BISTI GALLUP

11. County or Parish, State

SAN JUAN, N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☐ Subsequent Report
☒ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- (1) SET CIBP AT 5127'.
- (2) LOAD HOLE AND PRESSURE TEST (OK).
- (3) SPOT 25sk PLUG THROUGH TUBING ON TOP OF CIBP.
- (4) POOH TO 4200', SET 24sk PLUG.
- (5) POOH TO 2410', SET 13sk PLUG.
- (6) POOH TO 1700', SET 35sk PLUG.
- (7) PERFORATE AT 908'. COUEDN'T PUMP INTO FORMATION OR CIRCULATE.
- (8) RIH TO 960', SET 26sk PLUG.
- (9) PERFORATE AT 274'. COULDN'T CIRCULATE.
- (10) PERFORATE AT 220'. CIRCULATE AND PUMP 95sks CEMENT. CIRCULATED 2BBLS GOOD CEMENT.
- (11) CUT CASING STRINGS AND INSTALL DRY HOLE MARKER.

U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SANDOZ

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

14. I hereby certify that the foregoing is true and correct

Signed A. Chas. Coleman

Title Vice-President

Date 7-7-94

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date JUL 08 1994

APPROVED

NOT TO BE REPRODUCED

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

NM000